FAMILY COMPANIES

Service Specials



WIPER BLADE & WASHER FLUID FILL \$29 PLUS PARTS COST

LOAD TEST & CHECK BATTERIES \$59 (REPLACE 3 OR MORE BATTERIES AFTER TEST, LOAD TEST IS FREE)

BRAKE SHOE/PAD INSPECTION \$59 (VISUAL CHECK ONLY)

PRESSURE CHECK \$99 COOLING SYSTEM

FIFTH WHEEL ADJUSTMENT \$99

CLUTCH ADJUSTMENT \$99

A/C SYSTEM PRESSURE CHECK \$219

GREASE CHASSIS \$99

LUBE OIL LEVEL CHECK \$59 (INCLUDES POWERSTEERING, TRANSMISSION, DIFFERENTIAL, STEER HUBS)

AIR DRYER INSPECTION & REPLACE CARTRIDGE \$219 (INCLUDES RESETTING SERVICE INTERVAL ON ELECTRIC AIR DRYERS) ★ ADD PURGE VALVE FOR ADDITIONAL \$39 PLUS PARTS COST

Replacement Repairs

(PRICES INCLUDE LABOR COST FOR STANDARD INSTALLATIONS ONLY)

CABIN AIR FILTER REPLACEMENT \$59

SHOCK REPLACEMENT \$59 MUDFLAP REPLACEMENT \$99 PLUS PARTS COST

FUEL FILTER REPLACEMENT \$99

BATTERY REPLACEMENT \$219 (STANDARD INSTALLATION FOR UP TO 4 BATTERIES)

Albert Lea | Barron | Cloquet | Coon Rapids | Durand | Madison | Mankato | Northfield Owatonna | Red Wing | Sauk Centre | Sioux Falls | South St. Paul | Superior | Winona RIHMKENWORTH.COM | 800.988.8235